



Macalder Tailings Re-treatment
Carbon-in-Leach Flow Diagram