Figure 2: Gold recovery from bottle roll leaching of the fresh ore from the drilling programme