

Figure 1. Kapunda Location Map




Figure 2: Old Kapunda Mine Area – “Copper Range Limited Progress Report 14 December 2007”




Figure 3: Old Kapunda Mine Area cross section 8300N "Copper Range Limited Progress Report 14 December 2007"




Figure 4. Schematic of Insitu Recovery process

